

Figure 7. Acoustic-televiewer log of fracture zones and vertical-flow direction and rate as measured with the heat-pulse flowmeter in well P899 at Mahopac.